From: bob_belzarini@agilent.com

Sent: Thursday, October 29, 2009 9:55 AM

To: Hanchett, James (DPH)

Subject: 5972MSD

Hi Jim,

Just another thought. The lens insulator Part G3170-20530 (\$330.00) could also cause some problems with shorting out the lenses due to age. If you want I can send you one to try. Unfortunately if it doesn't fix the problem, you own it.

Or just wait for me to come in.

Either way let me know.

Thanks,

Bob

Bob Belzarini

Field Service Engineer Agilent Technologies 40 Shattuck Road Andover, Mass. 01810 bob belzarini@agilent.com 978-681-2109 Voicemail Service 1-800-227-9770